




# Wheel Check Loose Wheel Nut Indicators



## Get a Quick Visual of a Loose Wheel Nut

### TOP FEATURES & BENEFITS

- **QUICK VISUAL:** Used to identify a loose wheel nut with a simple visual inspection.
- **EASY TO USE:** When placed in a uniform position, the wheel check will appear out of sequence if nut is loose.
- **DETECT EXCESSIVE HEAT:** Also used to detect excessive heat in the event of a binding brake or seized bearing.
- 100 per bag.



Que-Mont No.	Mfg. No.	Description
21TW-WLCH-G	WLCH-G	Wheel Check Loose Wheel Nut Indicator - 1"
21TW-WLCH-AA	WLCH-AA	Wheel Check Loose Wheel Nut Indicator - 1-1/2"
21TW-WLCH-B	WLCH-B	Wheel Check Loose Wheel Nut Indicator - 33mm
21TW-WLCH-C	WLCH-C	Wheel Check Loose Wheel Nut Indicator - 7/8"

The use of wheel checks does not guarantee wheel-offs will not occur.

**Que-Mont Equipment Inc.**  
7475 Boulevard Thimens  
St. Laurent, Quebec H4S 2A2  
Tel: 514.331.0302 | Fax: 514.745.3109  
Email: info@quemont.com

**CALL 1-800-361-1932  
to place your order!**

[www.quemont.com](http://www.quemont.com)